



PORT OF LONDON  
AUTHORITY

Port of London Authority  
Chart Correction Advice  
Date: 22nd January, 2018




**CCA No: 2018/01**

Chart: Halfway Reach

The accompanying block correction shows:  
Revised soundings & contours around Southern Outfall Jetty

PLA Chart No. 327  
HO Ref No. 113-327-190  
Previous Chart Correction: 2014/39



For further information see the PLA hydrographic service website:  
<http://www.pla.co.uk/Safety/PLA-Hydrographic-Service-Published-Surveys>

HYDROGRAPHIC SERVICE  
ISO FORM 425