

Port of London Authority Chart Correction Advice Date: 22nd July, 2021




CCA No: 2021/20

Chart: Limehouse Reach

PLA Chart No. 319 HO Ref No. 113-319-130 Previous Chart Correction: 2021/10

The accompanying block correction shows: Revised Topography & Depths in and around Limekiln Dock and chart notes



For further information see the PLA hydrographic service website:

http://www.pla.co.uk/Safety/PLA-Hydrographic-Service-Published-Surveys